

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	2.76
1	Curb	Cock Valve T.S. & V.	3/4" in.	\$	3.49
1	Service box Old returned	Short 3/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway		\$	4.74
35	Ft.	Copper Pipe at	3/4" in. 38	\$	13.30
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
5	Hrs. Water Maint. Man-1	at	1.52	\$	7.60
13	Hrs. Water Maint. Man-2	at	1.24	\$	16.12
41	Hrs. Labor-	at	1.13	\$	46.33
	Hrs. Labor-	at		\$	
3	Hrs. Compressor	at	1.50	\$	4.50
	Compensation Ins.	at \$4.06 per C.		\$	3.09
	Trucking			\$	1.02
	Pav't Patch			\$	25.76
	Tap by Giggard	4-2-53		\$	
	O'head			\$	
				\$	128.69

10293

70-53

St. Warren
-Pt.
Ave. No. 195

Name of Owner Culligan

Labor and Mat'l. Report Apr. 2 1953

10" Main Elev. of Main at tap 5 1/2'

Gate at ● Gate at ●

3/4" Copper 35' to main

● Curb Box

Tax ID# 303.18-19-9

LSM-5C 5 18-48