

Labor and Materials

No.	Copper } Connection.....	\$	
	Lead }	\$	
1	Curb { Cook Valve } 1 1/4" in.....	\$	2.82
1	Service Box { Short 3 1/2 x 4 1/2 }	\$	2.63
	Old returned { Long 4 1/2 x 5 1/2 }	\$	
33	Ft. 1 1/4" in. { Copper Galv. Iron } Pipe at.....	\$	7.26
	Nipples..... in. at.....	\$	
1	Bushings. 1 1/4" to 1" in. at.....	\$	0.08
	Red'g } Couplings..... to..... in. at.....	\$	
	Inc'g }	\$	
	Union..... in. at.....	\$	
	Meter..... in. at.....	\$	
	Lbs. Br. Stone at.....	\$	
	Lbs. Sand at.....	\$	
	Bags Cement at.....	\$	
	Paving Brick { Mack Red Asphalt } at.....	\$	
	Lead Joints at.....	\$	
	Leadite Joints at.....	\$	
20	Hrs. Foreman at... 62.5	\$	12.50
23	Hrs. Common Labor at... 5.0	\$	11.50
10	Hrs. Common Labor at... 4.06	\$	4.06
	Hrs. Mason at.....	\$	
	Hrs. Mason's Helper at.....	\$	
	Hrs. Compressor at.....	\$	
	Compensation Ins.....	\$.25
	Trucking.....	\$	1.00
	Builders' Use of Water.....	\$	

Total \$ 42.60
63.55
106.15

Paul Patcher

26-87

Labor and Material Report

1926

July 24
1" main & 1 1/4" pipe Renewal 1927
Mason et



10' Main

Elev. of Main at tap 4.4 ft

Gate at ●

● Gate at

1 1/4" GALV Curb Box
33' to main

TAX ID# 303.18-19-8