

Labor and Materials

✓	Copper } Connection.....	1"	\$ 3.81
✓	Lead }		
✓	Curb { Cock Valve T.S.&V. }	1" in	\$ 3.59
	Service Box { Short 3 1/2 x 4 1/2 }		\$ 1.36
	Old returned { Long 4 1/2 x 5 1/2 }		
		Butt or Rivet	
✓	13 Ft. 1" in. { Copper Galv. Iron Cast Iron } Pipe at	22	\$ 2.82
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g } Couplings	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick { Mack Red Asphalt } at		\$
	Lead Joints at		\$
	Leadite Joints at		\$
1 1/2	Hrs. Foreman at		\$ 11.25
8 1/2	Hrs. Common Labor at		\$ 3.83
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Masons Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins		\$ 0.46
	Trucking		\$ 1.00
	Builders Use of Water Patch		\$ 9.00

Total \$ 37.12

33-7

Labor and Material Report

Jan 23 1931

1" Tap 12+19 Warren St



Curb Box

10" Main

Elev. of Main at tap 5'

Gate at

1" COPPER 13' to MAIN Gate at

Curb Box

old Tap Shut off at Main

TAX ID# 303.17-16-12

70