

LABOR AND MATERIALS

1	Copper	{ Connection	3/4	\$	2.29
	Lead				
1	Curb	{ Cock Valve T.S. & V.	3/4 in.	\$	2.70
1	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	4.25
11	Ft.	{ Copper G.I. C.I.	3/4 in. } Pipe at 25	\$	3.85
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	{ Coupl'gs	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
10	Hrs. Water Maint. Man-2	at	1.02	\$	10.20
8	Hrs. Labor	at	91	\$	7.28
	Hrs. Labor	at		\$	
2	Hrs. Compressor	at	1.20	\$	2.40
	Compensation Ins. at \$	per C.		\$.39
	Trucking			\$	1.39
	Pav't Patch			\$	13.44
	<i>Tap by Neuman</i>				\$
	O'head			\$	
				\$	47.80

St. _____
 Pl. _____
 Ave. No. 224

Name of Owner
Isaac

Labor and Mat'l. Report June 20 1950

224
10'2" 21'11"
● Curb Box

10 Main

Gate at ●

3/4" Copper

Elev. of
Main at tap 6

● Gate at

11' to main

● Curb Box

10/22 - Not on map

LSM-5C 10-21-49