

Labor and Materials

| | | | | |
|-------|-----------------------------|---|-------------------|----------|
| 1 | Copper | Connection..... | 3 | \$ 1.25 |
| 1 | Curb | { Cock Valve T.S.C.V. } | 1 | \$ 1.70 |
| 27 | Service Box Old returned | { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Bell, or Rdwr. } | 1 | \$ 1.37 |
| 27 | Ft. 3/4 in. | { Copper Galv. Iron Cast Iron } | Pipe at 1 1/2 in. | \$ 2.97 |
| | Nipples | in. at | | \$ |
| | Bushings | to in. at | | \$ |
| | Red'g Inc'g | { Couplings..... to in. at | | \$ |
| | Union | in. at | | \$ |
| | Meter | in. at | | \$ |
| | Lbs. Br. Stone | at | | \$ |
| | Lbs. Sand | at | | \$ |
| | Bags Cement | at | | \$ |
| | Paving Brick | { Mack Red Asphalt } | at | \$ |
| | Lead Joints | at | | \$ |
| | Leadite Joints | at | | \$ |
| 3 | Hrs. Foreman | at | 6 1/2 hr. | \$ 1.98 |
| 13 | Hrs. Common Labor | at | 45 | \$ 5.85 |
| | Hrs. Common Labor | at | | \$ |
| | Hrs. Mason | at | | \$ |
| | Hrs. Masons Helper | at | | \$ |
| | Hrs. Compressor | at | | \$ |
| | Compensation Ins | | | \$ 2.9 |
| | Trucking | | | \$ 1.- |
| | Builders Use of Water | Patch | | \$ 5.- |
| Total | | | | \$ 21.31 |

1935-9

Labor and Material Report

1935



6 Main Elev of Main at tap 5

Gate at ● Gate at ●

7/4" Copper 27' to main

● Curb Box

old Tap shut off main

shut off at curb 8-27-71

House Razed

TAX ID # 302.20-24-12