

LABOR AND MATERIALS

Copper	} Connection	_____	\$ _____				
Lead							
Curb	} Cock Valve T. S. & V.	} _____ in.	\$ _____				
				Service box	{ Short 3½ x 4½ Long 4½ x 5½	} _____	\$ _____
17.8 Ft.	1 in.	{ Copper C.I. C.I.	} Pipe at _____ \$ _____				
Nipples	in. at _____		\$ _____				
Bushings	to _____ in. at _____		\$ _____				
Red'g } Inc'g }	Coupl'gs _____ to _____ in. at _____		\$ _____				
Union	in. at _____		\$ _____				
Meter	in. at _____		\$ _____				
Lead Joints	at _____		\$ _____				
Compound Joints	at _____		\$ _____				
Maintenance Foreman	_____		\$ _____				
Hrs. Water Maint. Man	—1 at _____		\$ _____				
Hrs. Water Maint. Man	—2 at _____		\$ _____				
Hrs. Garage Foreman	_____ at _____		\$ _____				
Hrs. Labor	_____ at _____		\$ _____				
Hrs. Compressor	at _____		\$ _____				
Compensation Ins.	at \$ _____ per C		\$ _____				
Trucking	_____		\$ _____				
Pav't Patch	_____		\$ _____				
O'head	_____		\$ _____				

West

Washington

St. Pt. Ave. No. 1

Name of Owner
Cobby Pontiff et al.

Labor and Mat'l. Report July 1986

BKD.

1 1/2" FROM CURB
65.5' HYD.
Curb Box 8

WASH. ST.

GLEN ST.

Main Elev. of Main at tap _____

Gate at • Gate at
1" Copper 17'8" to main

• Curb Box

TAX ID # 302.20-16-15