

LABOR AND MATERIALS

1	Copper	{	Connection	3/4"	\$	2.29
	Lead					
1	Curb	{	Cock	3/4" in.	\$	2.70
			Valve			
			T.S.&V.			
1	Service box	{	Short 3 1/2 x 4 1/2		\$	
	Old returned		Long 4 1/2 x 5 1/2		\$	4.25
			Buff or Rdway			
20	Ft.	{	Copper	3/4 in.	\$	7.02
			Curb			
			Pipe at	35	\$	
	Nipples		in. at		\$	
	Bushings		to in. at		\$	
	Red'g	{	Coupl'gs	to in. at	\$	
	Inc'g					
	Union		in. at		\$	
	Meter		in. at		\$	
	Lead Joints at				\$	
	Compound Joints at				\$	
	Hrs. Water Maint. Man		1 at		\$	
7	Hrs. Water Maint. Man		2 at	1.02	\$	7.14
26	Hrs. Labor		at	91	\$	18.20
	Hrs. Labor		at		\$	
2	Hrs. Compressor at			1.20	\$	2.40
	Compensation Ins. at		\$ 2.22 per C.		\$.56
	Trucking				\$	1.00
	Pav't Patch				\$	8.10
	Tap by Moquin				\$	
	O'head				\$	
					\$	53.64

St.
Pl.
Ave. No. 15

W. Washington

Name of Owner
MOSS

Labor and Mat'l. Report Sept. 12 1950

4" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

3/4" copper 20' to main

● Curb Box

House Razed 1970
10/22 - not on map

LSM-8C 10-21-49