

LABOR AND MATERIALS

Copper	} Connection	_____	\$ _____	
Lead				
Curb	} Cock	_____ in.	\$ _____	
				} Valve
Service box	} Short 3½ x 4½ }	_____	\$ _____	
Old returned		} Long 4½ x 5½ }	_____	\$ _____
Ft. ^{3/4} in.	} Copper		} Pipe at _____	\$ _____
		} Gal.		
Nipples	_____ in. at _____		\$ _____	
Bushings	_____ to _____ in. at _____	\$ _____		
Red'g	} Coupl'gs _____ to _____ in. at _____	\$ _____		
Inc'g				
Union	_____ in. at _____	\$ _____		
Meter	_____ in. at _____	\$ _____		
		\$ _____		
Compound Joints	at _____	\$ _____		
Maintenance Foreman		\$ _____		
Hrs. Water Maint. Man—1	at _____	\$ _____		
Hrs. Water Maint. Man—2	at _____	\$ _____		
Hrs. Garage Foreman	at _____	\$ _____		
Hrs. Labor—	at _____	\$ _____		
Hrs. Compressor	at _____	\$ _____		
		\$ _____		
Trucking		\$ _____		
Pav't Patch		\$ _____		
		\$ _____		
		\$ _____		
		\$ _____		
		\$ _____		

WATER

St. ~~11~~ No. 12
Ass.

Name of Owner

LOUIS LAROCK

Labor and Mat'l. Report

9-30 1998

● Curb Box

Main

Elev. of
Main at tap

Gate at ●

● Gate at

● Curb Box