

LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	}	Cock Valve T. S. & V.			\$
Service Box	}	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway			\$
Old returned					
Ft. _____ in.	}	Copper Galv Iron Cast Iron			\$
Nipples _____ in.					\$
Bushings _____ to _____ in.					\$
Red'g Inc'g	}	Couplings			\$
Union _____ in.					\$
Meter _____ in.					\$
Lead Joints					\$
Leadite Joints					\$
Hrs. Foreman					\$
Hrs. Chauffeur					\$
Hrs. Tapper					\$
Hrs. Labor					\$
Hrs. Labor					\$
Hrs. Compressor					\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$

St. _____
 Pt. _____
 Ave. No. 23

Webster

Name of Owner _____

TAX ID # 302.11-6-13

Labor and Mat'l. Report 7-19-39 19__

● Curb Box

Main	Elev. of Main at tap
Gate at ●	● Gate at

● Curb Box

J. J. Burns