

LABOR AND MATERIALS

Copper	Lead	Connection	-----	\$	
Curb	{ Cock Valve T. S. & V. }	-----	in. -----	\$	
Service Box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway }	-----		\$	
Old returned		-----			
Ft. -----	in. -----	{ Copper Galv Iron Cast Iron }	Pipe at -----	\$	
Nipples	-----	in. at -----		\$	
Bushings	-----	to -----	in. at -----	\$	
Red'g Inc'g	{ Couplings	-----	to -----	in. at -----	\$
Union	-----	in. at -----		\$	
Meter	-----	in. at -----		\$	
Lead Joints	-----	at -----		\$	
Leadite Joints	-----	at -----		\$	
Hrs. Foreman	-----	at -----		\$	
Hrs. Chauffeur	-----	at -----		\$	
Hrs. Tapper	-----	at -----		\$	
Hrs. Labor	-----	at -----		\$	
Hrs. Labor	-----	at -----		\$	
Hrs. Compressor	-----	at -----		\$	
Compensation Ins.	-----			\$	
Trucking	-----			\$	
Builders Use of Water	-----			\$	
	-----			\$	
	-----			\$	
	-----			\$	
	-----			\$	
	-----			\$	
	-----			\$	
	-----			\$	
	-----			\$	

St. _____
Pt. _____
Ave. No. 56?

Name of Owner
Lockhart

Labor and Mat'l. Report 7-19-39 19

L4.
Webster
Ave.

146'

● Curb Box

Main	Elev. of Main at tap
Gate at ●	● Gate at

● Curb Box

VACANT Lot Tap