

LABOR AND MATERIALS

Copper } Connection _____	\$ _____
Lead } _____	\$ _____
Curb } Cock _____	in. \$ _____
} Valve _____	
} T.S. & V. _____	
Service box { Short 3½ x 4½ _____	\$ _____
Old returned { Long 4½ x 5½ _____	
} Buff or Rdway _____	
32 Ft. ¾ in. { Copper _____	Pipe at \$ _____
} C.I. _____	
} C.I. _____	
Nipples _____ in. at _____	\$ _____
Bushings _____ to _____ in. at _____	\$ _____
Red'g } Coupl'gs _____ to _____ in. at _____	\$ _____
Inc'g } _____	
Union _____ in. at _____	\$ _____
Meter _____ in. at _____	\$ _____
Lead Joints at _____	\$ _____
Compound Joints at _____	\$ _____
Maintenance Foreman _____	\$ _____
Hrs. Water Maint. Man-1 at _____	\$ _____
Hrs. Water Maint. Man-2 at _____	\$ _____
Hrs. Garage Foreman _____ at _____	\$ _____
Hrs. Labor _____ at _____	\$ _____
Hrs. Compressor at _____	\$ _____
Compensation Ins. at \$ _____ per C _____	\$ _____
Trucking _____	\$ _____
Pav't Patch _____	\$ _____
_____	\$ _____
_____	\$ _____
_____	\$ _____
O'head _____	\$ _____
_____	\$ _____

~~St.~~
~~Pl.~~
 Ave. No. 41

Western (S)
 Name of Owner Roy Kline

TAX ID # 309.7-10-31 1986
 Labor and Mat'l. Report

12" Main Elev. of Main at tap _____
 Gate at • • Gate at _____
32' to main
 • Curb Box

LSM-5C-6-1-67