

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Lead	Cock	3/4"	\$
1	Curb	Valve	3/4" in.	\$
		T. S. & V.		\$
1	Service box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		\$
		Buff or Rdway		\$
36	Ft. 3/4 in.	Copper	Pipe at	\$
		C-I		\$
		C-I		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			\$
	Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Giesford & Co			\$
		6-24-57		\$
				\$
	O'head			\$
				\$

(North) ✓

Western Ave. No. 2

Name of Owner
M. Armstrong

Labor and Mat'l. Report June 24 1957

western Ave. North

12" Main Elev. of Main at tap 4 1/2"

Gate at • • Gate at

36' to main

• Curb Box

TAX ID # 302.19-12-1

LSM-SC-2-5 56