

LABOR AND MATERIALS

/	Copper Lead	Connection $\frac{3}{4}$	\$	2.94	
/	Curb	{ Clock Valve T. S. & V. } $\frac{3}{4}$ in.	\$	3.71	
/	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway }	\$	5.90	
15	Ft. $\frac{3}{4}$ in.	{ Copper Galv. Iron Cast Iron. } Pipe at 30	\$	4.50	
.....	Nipples in. at	\$		
.....	Bushings to	\$		
.....	Red'g Inc'g	{ Couplings to	\$		
.....	Union in. at	\$		
.....	Meter in. at	\$		
.....	Lead Joints at	\$		
.....	Compound Joints at	\$		
.....	Hrs. Foreman at	\$		
2	Hrs. Chauffeur at	W.M.M. 2 91	\$	1.82	\$ 5.25
.....	Hrs. Tapper at	\$		
5	Hrs. Labor at 20	\$	4.00	
.....	Hrs. Labor at	\$		
.....	Hrs. Compressor at	\$		
.....	Compensation Ins.	\$	1.13	
.....	Trucking	\$	1.13	
.....	Builders Use of Water	\$		
.....	Tap by McGinnis	\$		
.....	\$		
.....	\$		
.....	\$		
.....	\$	24.00	

33 North,

St. _____
 Pl. _____
 Ave. No. 21

Name of Owner
Cashley

Labor and Mat'l. Report *April 23 1948*

12 Main Elev. of Main at tap 5

Gate at ● ● Gate at

15' to main

● Curb Box

TAX ID # 302.19-13-14

LSM-5C-6-1-48