

LABOR AND MATERIALS

| | | | | | |
|------------|-------------------------------------|-----------------------|------------|--|----------------------|
| 1 | Copper | { Connection | 3/4" | | \$ 2.04 |
| | Lead | | | | |
| 1 | Curb | { Cock Valve | 3/4 in. | | \$ 3.54 |
| | | { T. S. & V. | | | |
| 1 | Service box | { Short 3 1/2 x 4 1/2 | | | \$ 4.70 |
| | Old returned | { Long 4 1/2 x 5 1/2 | | | |
| | | { Buff or Rdway | | | |
| 36 | Ft. 3/4 in. | { Copper | | | \$ 8.75 |
| | | { G. I. | Pipe at 35 | | |
| | | { C. I. | | | |
| 11 ft @ 40 | Nipples | | in. at | | \$ |
| | Bushings | | to in. at | | \$ |
| | Red'g Inc'g | { Coupl'gs | to in. at | | \$ |
| | Union | | in. at | | \$ |
| | Meter | | in. at | | \$ |
| | Lead Joints at | | | | \$ |
| | Compound Joints at | | | | \$ |
| | Hrs. Water Maint. Man-1 at | | | | \$ |
| | Hrs. Water Maint. Man-2 at | | | | \$ |
| 3 | Hrs. Labor AM | | at 1.26 | | \$ 3.78 ^N |
| 2 | Hrs. Labor | | at 1.02 | | \$ 2.04 |
| | Hrs. Compressor at | | | | \$ |
| | Compensation Ins. at \$ 2.66 per C. | | | | \$ 15 |
| | Trucking | | | | \$ 1.00 |
| | Pav't Patch | outside city | | | \$ |
| | O'head | | | | \$ |
| | Tap by Gifford | | | | \$ 27.00 |
| | 4/10/51 | | | | 4.40 |

34-1701 North

St. 10
Pl. 16
Ave. No. 16

Name of Owner
Koppel

Labor and Mat'l. Report 4 - 10 - 19 51

● Curb Box

12" Main Elev. of Main at tap 4 1/2'

Gate at ● ● Gate at

TAX ID# 302.19-12-5

● Curb Box

LSM-5C 10-21-49