

**Labor and Materials**

1	Copper } Connection	3/4	\$ 2.60
	Lead } .....		
	Curb } Cock		
	} Valve		
	} T. S. & V. in	3/4	\$ 2.30
1	Service Box } Short 3 1/2 x 4 1/2		
	Old returned } Long 4 1/2 x 5 1/2		
	} Buff. or Rdway		\$ 1.40
2 1/4	Ft. in. } Copper	3/4	
	} Galv. Iron		
	} Cast Iron		
	} Pipe at		\$ 6.36
	Nipples in. at		\$
	Bushings to in. at		\$
	Red'g } Couplings		
	Inc'g } to in. at		\$
	Union in. at		\$
	Meter in. at		\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack		
	} Red		
	} Asphalt		\$
	Lead Joints at		\$
	Leadite Joints at		\$
7	Hrs. Foreman at		\$ 4.38
20	Hrs. Common Labor at		\$ 9.13
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
3	Hrs. Compressor at		\$ 4.50
	Compensation Ins		\$ .33
	Trucking		\$ 1.19
	Builders' Use of Water Patch		\$ 25.00
Total \$			56.02

29-177 **31** **31** **1** 19**29**

Labor and Material Report *Out*

25 *William st*

4 Main Elev of Main at tap

Gate at ● ● Gate at

*24' to main*

● Curb Box

*Old tap shut off*

TAX ID # 302.16-17-11