

LABOR AND MATERIALS

1	Copper	{	Connection $\frac{3}{4}"$	\$ 2.76
1	Lead	{	Cock	
		{	Valve	
1	Curb	{	T. S. & V. $\frac{3}{4}$ in.	\$ 3.49
1	Service box	{	Short $3\frac{1}{2} \times 4\frac{1}{2}$	
	Old returned	{	Long $4\frac{1}{2} \times 5\frac{1}{2}$	474
		{	Buff or Rdway	
11	Ft. $\frac{3}{4}$ in.	{	Copper	Pipe at 38	\$ 4.18
		{	G. I.	
		{	C. I.	
.....	Nipples	in. at	\$
.....	Bushings	to in. at	\$
.....	Red'g	\$
.....	Inc'g Coupl'gs	to in. at	\$
.....	Union	in. at	\$
.....	Meter	in. at	\$
.....	Lead Joints	at	\$
.....	Compound Joints	at	\$
.....	Hrs. Water Maint. Man-1	at	\$
4 1/2	Hrs. Water Maint. Man-2	at 1.24	\$ 5.58
19	Hrs. Labor	at 1.13	\$ 21.47
.....	Hrs. Labor	at	\$
.....	Hrs. Compressor	at	\$
.....	Compensation Ins. at \$ 4.40 per C.	\$ 1.19
.....	Trucking	\$ 1.00
.....	Pav't Patch	\$ 9.80
	Tap by Gridford 8.6.53	\$
.....		\$
.....		\$
.....	O'head	\$
					\$ 54.21

44.41

2.706

69-53

St. WILLIAM No. 32

Name of Owner SHARLAND.

Labor and Mat'l. Report AUG. 6. 1953

RE-NEWAL.

4" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

11' to MAIN

● Curb Box

TAX ID# 302.16-15.42

LSM-5C 5 15-48