

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$ 1.31
1	Curb	Cock Valve F. S. & V.	3/4 in.	\$ 1.75
1	Service Box Old returned	Short 3/2x4 1/2 Long 4/2x5 1/2 Buff. or Rdway		\$
24	Ft.	in.	3/4	Pipe at 18 \$ 4.32
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
5	Hrs. Chauffeur	at	6 2/2	\$ 3.13
8	Hrs. Tapper	at		\$ 5-
8	Hrs. Labor	at	45	\$ 3.60
	Hrs. Labor	at		\$
1 1/2	Hrs. Compressor	at	6 2/2	\$ 94
	Compensation Ins.			\$ 1.36
	Trucking			\$ 9-
	Builders Use of Water	Patch		\$
	Taphy, Penco			\$
				\$
				\$
				\$
				\$
				\$ 30.41

7 5 - - 1940

St. 33

Ave. No. 27

William

Name of Owner

Bloom

Labor and Mat'l. Report

JUNE 27 1940



4 Main Elev. of Main at tap 5-

Gate at ● ● Gate at

24' to MAIN

● Curb Box

TAX ID# 302.16-17-10

Handwritten initials