

# LABOR AND MATERIALS

1	Copper Lead	{ Connection $\frac{3}{4}$ "	\$ 229
1	Curb	{ Cock Valve T.S. & V. } $\frac{3}{4}$ " in.	\$ 270
1	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway. }	\$ 425
256	Ft. $\frac{3}{4}$ in.	{ Copper G.I. C.F. } Pipe at 35	\$ 910
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	{ Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints at		\$
	Compound Joints at		\$
	Hrs. Water Maint. Man-1 at		\$
11	Hrs. Water Maint. Man-2 at	1.02	\$ 11.22
11	Hrs. Labor at	91	\$ 10.01
	Hrs. Labor at		\$
2	Hrs. Compressor at		\$ 240
	Compensation Ins. at \$	per C.	\$ 47
	Trucking		\$ 1.00
	Pav't Patch		\$ 11.76
			\$
			\$
			\$
	O'head		\$
			\$
			\$ 55.20

156-1000 Renewal

St. William  
 Pt. Howard  
 Ave. No. 37

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report July 24 1950

#37

43'6" 34'2"

• Curb Box

---

4" Main Elev. of Main at tap 5'

Gate at • Gate at •

26' to main

• Curb Box

TAX ID# 302.16-17-8

LSM-5C 10-21-49