

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$	1.96
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$	1.33
1	Service Box Old returned	Short 3/2x4 1/2 Long 4/2x5 1/2 Buff. or Rdway		\$	1.35
24	Ft.	3/4 in.	Copper Galv. Iron. Cast Iron. Pipe at 15	\$	3.60
	Nipples	in.	at	\$	
	Bushings	to	in. at	\$	
	Red'g Inc'g	Couplings	to in.	at	\$
	Union	in.	at	\$	
	Meter	in.	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
	Hrs. Foreman	at		\$	
5	Hrs. Chauffeur	at	6 2/4	\$	3.13
13	Hrs. Tapper	at	"	\$	8.12
13	Hrs. Labor	at	45	\$	5.85
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$.52
	Trucking			\$	1 -
	Builders Use of Water	Patch		\$	1 -
	Taply Permit			\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	30.86

St. **49**
 Pt. **34**
 Ave. No. **34**
 Name of Owner **Burnham**
Tap made
 Labor and Mat'l Report **Dec. 5** 19**36**

4' Main **TAP ON VANDERHEYDEN** Elev. of Main at tap **4'**
 Gate at ● Gate at ●
24' to MAIN
 ● Curb Box
 TAX ID # 302.16-16-12