

### LABOR AND MATERIALS

Copper	}	Connection			\$	
Lead						
Curb	{	Cock Valve T. S. & V.			\$	
Service Box			}	Short 3 1/2 x 4 1/2		\$
Old returned					Long 4 1/2 x 5 1/2	
		Buff. or Rdway				
Ft. <sup>3/4</sup> in.	{	Copper Galv Iron Cast Iron			\$	
			Pipe at			
Nipples				\$		
Bushings				\$		
Red'g Inc'g	}	Couplings			\$	
			to			
Union				\$		
Meter				\$		
Lead Joints				\$		
Leadite Joints				\$		
Hrs. Foreman				\$		
Hrs. Chauffeur				\$		
Hrs. Tapper				\$		
Hrs. Labor				\$		
Hrs. Labor				\$		
Hrs. Compressor				\$		
Compensation Ins.				\$		
Trucking				\$		
Builders Use of Water				\$		
				\$		
				\$		
				\$		
				\$		

St. 9  
 Pl. 3 1/2  
 Ave. No. 3 1/2

Name of Owner William

---

Labor and Mat'l. Report May 5 1939

TAX ID # 302.16-17-22

Main
Elev. of Main at tap

---

Gate at ●
● Gate at

---

● Curb Box

Renewal Tap  
Fall 1986