

LABOR AND MATERIALS

1 Copper Lead { Connection $\frac{3}{4}$ " } \$
 1 Curb { Cock Valve T.S. & V. } $\frac{3}{4}$ in. Oriseal. \$
 1 Service Box { Short $3\frac{1}{2} \times 4\frac{1}{2}$ } \$
 Old returned { Long $4\frac{1}{2} \times 5\frac{1}{2}$ } \$
 { Buff. or Rdway. }
 19 Ft. $\frac{3}{4}$ in. { Copper Galv. Iron Cast Iron } Pipe at \$
 Nipples in. at \$
 Bushings to in. at \$
 Red'g Inc'g { Couplings to in. at } \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Leadite Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 Hrs. Labor at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 Tap by Gifford + Co \$
 5-7-64. \$
 \$
 \$

St. Wilmot
 Pl. 15
 Ave. No. 15

Name of Owner Anthony J. Cardinale

Labor and Mat'l. Report May 7 1964

6" Main Elev. of Main at tap $4\frac{1}{2}$ '

Gate at ● Gate at ●

19' to MAIN

● Curb Box

TAX ID# 309.7-8-3