

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$ 1.31
1	Curb	Cock Valve T. S. & V.	$\frac{3}{4}$ in.	\$ 1.75
1	Service Box Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway		\$ 1.60
18	Ft.	$\frac{3}{4}$ in.	Copper Galv Iron Cast Iron	Pipe at 18 \$ 3.24
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
3	Hrs. Chauffeur	at	6.24	\$ 1.88
4	Hrs. Tapper	at		\$ 2.50
5	Hrs. Labor	at	.45	\$ 2.25
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 21
	Trucking			\$ 1-
	Builders Use of Water	Patch		\$ 5-
	Tap by Hessel			\$
				\$
				\$
				\$
				\$
				\$
				\$
				\$
				\$ 20.74

✓ 2 - - 1940

St. Wilmet

Pt. Ave. No. 17

Name of Owner O'Connor

Labor and Mat'l. Report Apr 27 1940

17'4" 23'8"
● Curb Box

6 Main Elev. of Main at tap 6

Gate at ● Gate at

18' to main

● Curb Box

TAX ID # 309.7-8-2

Take Bill 24