

LABOR AND MATERIALS

Copper	} Connection	_____	\$ _____		
Lead					
Curb	} Cock Valve T. S. & V.	_____ in.	\$ _____		
Service box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway	_____	\$ _____		
Old returned					
26 1/4 Ft.	} Copper G.I. C.I.	_____ in.	\$ _____		
3/4					
Nipples	_____ in.	at _____	\$ _____		
Bushings	_____ to _____	in. at _____	\$ _____		
Red'g	} Coupl'gs	_____ to _____	in. at _____		
Inc'g					
Union	_____	in. at _____	\$ _____		
Meter	_____	in. at _____	\$ _____		
Lead Joints	_____	at _____	\$ _____		
Compound Joints	_____	at _____	\$ _____		
Maintenance Foreman	_____	at _____	\$ _____		
Hrs. Water Maint. Man—1	_____	at _____	\$ _____		
Hrs. Water Maint. Man—2	_____	at _____	\$ _____		
Hrs. Garage Foreman	_____	at _____	\$ _____		
Hrs. Labor	_____	at _____	\$ _____		
Hrs. Compressor	_____	at _____	\$ _____		
Compensation Ins. at \$ _____	_____	per C _____	\$ _____		
Trucking	_____		\$ _____		
Pav't Patch	_____		\$ _____		
			\$ _____		
			\$ _____		
			\$ _____		
O'head	_____		\$ _____		
			\$ _____		

RR  
St. \_\_\_\_\_  
Pl. \_\_\_\_\_  
Ave. No. 2

---

Name of Owner  
Halter Fallman

---

Labor and Mat'l. Report June 22 1983

56' 11"      53' 10"  
● Curb Box

---

TAX ID # 303.9-7-40

\_\_\_\_\_ Main      Elev. of Main at tap \_\_\_\_\_

Gate at ●      ● Gate at \_\_\_\_\_

26' 4" to main

---

main tap      ● Curb Box

HOUSE ON CORNER OF SANFORD & WINDY HILL

Below TAP ON SANFORD (P.)

LSM-5C-6-1-67