

LABOR AND MATERIALS

1 Copper Connection $\frac{3}{4}$ " \$
 Lead }
 1 Curb Cock } $\frac{3}{4}$ " in. Oriseal \$
 Valve }
 T.S. & V. }
 1 Service box { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ }
 Old returned { Long $4\frac{1}{2}$ x $5\frac{1}{2}$ } \$
 Buff. or Rdway }
 30 Ft. $\frac{3}{4}$ " in. { Copper } Pipe at \$
 { G.I. }
 { C.I. }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g }
 Inc'g } Coupl'gs to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man-1 at \$
 Hrs. Water Maint. Man-2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C \$
 Trucking \$
 Pav't Patch \$
 Tap by Gifford & Co. \$
 6-1-64 \$
 O'head \$
 \$

Rd. Windy Hill
 St. Crackwell
 Pl. Devel.
 Ave. No. 23

Name of Owner McKenzie

Labor and Mat'l. Report June 1 1964

6" C.I. Main Elev. of Main at tap 5'4"

Gate at • Gate at •

Remeasured

3-16-66, • Curb Box

TAX ID# 303.9-8-25

LSM-BC-3-10-61