

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$
1	Service box -Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
8	Ft.	3/4 in. { Copper C.I. C.I.	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	1 at		\$
	Hrs. Water Maint. Man	2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Top by Gifford & Co.			\$
				\$
				\$
				\$
	O'head			\$
				\$

8-25-66

Rd.  
St.  
Pl.  
Ave. No. 36

Windy Hill

Name of Owner John Wheeler.

TAX ID# 303.5-2-7

Labor and Mat'l. Report Aug. 25 1966

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

8' to main

● Curb Box

LSM-5C-8-10-61