

Labor and Materials

1	Copper } Connection	3/4	\$ 3.20
	Lead }		
1	Curb } Cock	3/4 in.	\$ 1.00
	Valve }		
	P. S. & V. }		
1	Service Box } Short 3 1/2 x 4 1/2		\$ 1.20
	Old returned } Long 4 1/2 x 5 1/2		
		Buff. or Rdway	
7	Ft. 3/4 in. } Copper		\$ 1.56
		Galv. Iron	
		Cast Iron	
1	Nipples	3/4 in. at 3/4	\$ 1.0
1	Bushings	1 to 3/4 in. at	\$ 1.5
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick } Mack	at	\$
		Red	
		Asphalt	
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
4	Hrs. Common Labor	at 50	\$ 2.00
4	Hrs. Common Labor	at 40 5/8	\$ 1.63
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.	at 10	\$ 1.0
	Trucking	at 100	\$ 1.00
	Builders' Use of Water	at	\$
Total \$			

Labor and Material Report

1921

Nov 5 King St



4" Main

Elev. of Main at tap 4'

Gate at ●

Gate at ●

7' to main

● Curb Box

Old York Street  
off

TAX ID# 303.13-2-17