

LABOR AND MATERIALS

1 Copper } Connection <sup>3/4"</sup> \$ \_\_\_\_\_  
 Lead }  
 1 Curb } Cock } 3/4 in. \$ \_\_\_\_\_  
           } Valve }  
 Same } T.S. & V. }  
 Service box } Short 3 1/2 x 4 1/2 }  
 Old returned } Long 4 1/2 x 5 1/2 } \$ \_\_\_\_\_  
                   } Buff or Rdway }  
 25 Ft. <sup>3/4</sup> in. } ~~C.I.~~ } Pipe at \$ \_\_\_\_\_  
                   } ~~C.I.~~ }  
 Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs. \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Lead Joints at \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man-1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man-2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 Compensation Ins. at \$ \_\_\_\_\_ per C \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pay't Patch \$ \_\_\_\_\_  
 Tap by Giffard, \$ \_\_\_\_\_  
 Miller & Co. \$ \_\_\_\_\_  
 6-17+18-57 \$ \_\_\_\_\_  
 O'head \$ \_\_\_\_\_  
 \$ \_\_\_\_\_

St. Woodaid  
 Pt. 23  
 Ave. No. 23

Name of Owner Wm. H. Kingsley

Labor and Mat'l. Report June 18 1957

# 23

14' 6"

20' 1"

● Curb Box

10 Main Elev. of Main at tap 5'

Gate at ● ● Gate at

25' to MAIN

● Curb Box

TAX ID # 309.15-9-13

LSM-5C-2-5-56