

LABOR AND MATERIALS

1	Copper	Connection	3/4	\$	2.29
1	Lead			\$	2.70
1	Curb	Cock Valve - T.S. & V.	3/4 in.	\$	4.25
1	Service box	Short - 3 1/2 x 4 1/2		\$	4.25
	Old returned	Long - 4 1/2 x 5 1/2		\$	
		Buff or Rdway		\$	
10	Ft.	Copper		\$	3.50
		G.I.		\$	
		G.I.		\$	
		Pipe at	35	\$	3.50
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	Coupl'gs to in. at		\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man	1 at		\$	
11	Hrs. Water Maint. Man	2 at	1.02	\$	11.22
22	Hrs. Labor	at	91	\$	20.02
	Hrs. Labor	at		\$	
4	Hrs. Compressor	at	1.20	\$	4.80
	Compensation Ins.	at \$ per C.		\$	70
	Trucking			\$	6.75
	Pav't Patch			\$	
	Tax by <i>McGowan</i>			\$	
	O'head			\$	
				\$	57.23

1-2-1950

St. _____
Pl. _____
Ave. No. 8

Name of Owner
Cashion

Labor and Mat'l. Report Feb 9 1950

19'4" 18'5"
● Curb Box

TAX ID # 309.12-11-21

4 Main Elev. of Main at tap 5

Gate at ● ● Gate at

10' to MAIN

● Curb Box

NEW COPPER LINE - 1998
GALK. ON THEIR SIDE

LSM-5C 10-21-49