

LABOR AND MATERIALS

| | | | |
|----|----------------------------|--|--|
| 1 | ^{Bronze} Copper | } Connection ^{3/4"} | \$ |
| 1 | Lead | | \$ |
| 1 | Curb | } Cock Valve T.S. & V. ^{3/4"} in. | \$ |
| 1 | Service box | | } Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway |
| 11 | Old returned | | |
| 11 | 11 Ft. ^{3/4"} in. | } Copper G.I. G.I. | } Pipe at \$ |
| | Nipples | | |
| | Bushings | to in. at \$ | |
| | Red'g | } Coupl'gs to in. at \$ | |
| | Inc'g | | |
| | Union | in. at \$ | |
| | Meter | in. at \$ | |
| | Lead Joints | at \$ | |
| | Compound Joints | at \$ | |
| | Maintenance Foreman | \$ | |
| | Hrs. Water Maint. Man-1 | at \$ | |
| | Hrs. Water Maint. Man-2 | at \$ | |
| | Hrs. Garage Foreman | at \$ | |
| 8 | Hrs. Labor | at \$ | |
| | Hrs. Compressor | at \$ | |
| | Compensation Ins. | at \$ per C \$ | |
| | Trucking | \$ | |
| | Pav't Patch | \$ | |
| | O'head | \$ | |

St. Pl. Ave. No. 12

Woodlawn Ave.

Name of Owner John Carroll

Remeasured 9/21/54

Labor and Mat'l. Report 10-13 1925

4" Main

Elev. of Main at tap 4'

Gate at • Gate at 11' to main

• Curb Box

TAX ID # 309.12-11-23

L. M-5C-2-1-54